

5m,1.23.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Trp. S.Sr. "BINGERA" Rpt. Bsb. No. 1549

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

Action has been deferred in this case to allow of further examination in dry dock at the first favourable opportunity, after touching a river bank.

Some fire damage requires to be repaired at a convenient opportunity.

The Brisbane Surveyor now reports the vessel examined afloat and the fire damage repaired and a general examination made.

It is stated the vessel is to be laid up indefinitely.

It is submitted action be deferred.

J.S.P.
24.11.23.

Delete fire damage from S.R.List.



© 2021

Lloyd's Register
8410 FORM
Foundation