

TAYLOR,  
SURVEYOR,  
NAVAL ARCHITECTS

# Lloyd's Register of Shipping,

EAGLE STREET,

OFFICE NO. 552  
RESIDENCE NO. 145  
GRAPHIC ADDRESS  
SURVEYOR  
CODES:  
B.C. FIFTH EDITION

**LLOYD'S REGISTER,  
LONDON,**

BOX 465 G.P.O.

*Brisbane,* 12th October 1923

**REC'D 19 NOV 1923**

**ANS'D** \_\_\_\_\_

Dear Sir,

Regarding your letter of the 21st June having reference to my reports Nos. 1401 and 1465 on the s/s "BINGERA" I have to report that I approached Messrs. Macdonald Hamilton & Co. and they at once arranged to have the survey held.

The vessel has been laid up since 3/August, is still laid up and likely to be for sometime, drought and other conditions have led to the laying up of a number of steamers.

The reason why the steam test and floating of valves have not been carried out, is that the Marine Board Certificate is dated from then and for the same reason she has not been dry-docked.


Yours faithfully,

*A. S. Scott*  
Surveyor

A. Scott, Esq.,

Secretary,

LONDON. E.C.3.



© 2021

Lloyd's Register  
Foundation

W707-0149

Referred to Mr. S. A. Hill.

WAM

19 NOV 1923

F.O.C. PORTLAND

YACHTS

..PAC. JACOB.A

YACHTS

YACHTS

..PAC. JACOB.A

YACHTS

YACHTS

YACHTS

..PAC. JACOB.A

RECEIVED

Lloyd's Register Foundation

(X503)

Committee  
Second Survey  
Traveling Ex  
Special Damage  
WEEK IN  
Survey Fee (See  
General

this s  
survey

General

Inner Bottom  
Stringers  
Keelsons  
Floors  
Reverses Fram  
Frames  
Transoms  
Breakhooks &  
Rivets  
Caulking of d  
Outside Plasti  
Beams & Fast  
Coamings  
Waterways  
Caulking of  
Decks  
PRESENT C  
Faire  
Remo  
Renew  
SUMMARY  
deck

exam  
world  
ON DE  
was o  
requi  
and p  
REPAIR  
they  
In damag