

YLLOR,
OR.
VAL ARCHITECTS.
CE No. 562
RES. No. 1048
RESS:
OR."
SI
ND STANDARD.

Lloyd's Register of British & Foreign Shipping,

EAGLE STREET,

RST/CF

Brisbane, 25th February 1915

Sir,

Re S. S. "BINGERA"

Completed Reports 8 and 9 and forwarded under separate cover, I have seen the Anchor and Chain Certificates they are as follows :-

No.Cert.39023/4	each 120 fths. stud Link 1	¹³ / ₁₆	dated 13.9.14
" 54749	one anchor 39cwt.2qrs.0lbs	"	13.9.14
" 54750	" " 33 " - 26 "	"	
" 54770	" 38 " 1 26 "	"	15.9.14

The anchors and cables are on board and in good order.

I am, Sir,

Your Obedient Servant,

R. S. Langford

Surveyor.

A. Scott, Esq.,

Secretary,

LONDON. E.C.



© 2021

Lloyd's Register
Foundation

W707-0163

CS2
M
9.4.15

• Toy Story

[illegible]

LOR,
 R,
 ARCHITECT
 NO. 562
 RES. NO. 104
 ESS:
 3.75
 STANDARD.