

YLOR.

OR.

AL ARCHITECTS.

No. 562
RES. No. 1048

RESS;
OR."
The Com
livery in
Company
STANDARD.

ount of a
ission in
ogram is
the Com
service of

dress;
ing to

rates

arged
and
ate.

duced
tional
going

er

Lloyd's Register of British & Foreign Shipping, LONDON.

EAGLE STREET.

RECD 28 MAR 1915
RST/CF
ANSO

Brisbane, 15th February 1915

Sir,

S. S. "BINGERA"

I am forwarding by this mail the reports in connection with this vessel; Report 9 is not yet signed by Mr. Campbell, the Engineer Surveyor to the Marine Board, I have the permission of the Chairman for Mr. Campbell to sign, and the latter is willing, but he wants written authority and that is not yet forthcoming, and the matter has to be considered by the Board. Mr. Campbell was the only man outside of the Owners representative who was in the Boilers; therefore I have signed in pencil Mr. Campbell's name and sent the reports along to avoid further delay and next week I hope to be able to send a copy of same Rpt. 9 ~~but~~ properly signed. I have told the Chairman that Mr. Campbell will receive an honourarium as a fee, and have allowed for that; and regarding fees to be charged I am in something of a dilemma as to what to charge. I have made the total at 25 guineas dividing it as to £10. 10. 0 for the engines and boilers, and £15.15. 0 for hull equipment and freeboard, which I trust is in order. I am to meet the Manager of the A. U. S. N. Coy. here regarding this question, before putting in the account, meantime it will not show in my quarterly statement unless they are agreeable to that amount.

Trusting you will receive all in order,

I am, Sir,

Yours obedient servant,

A. Scott, Esq.,

Secretary,

LONDON. E.C.



R. S. [Signature]

Surveyor.

Lloyd's Register
Foundation

Encls/

W707-074

Referred to the Chief Engineer Surveyor.

MAR 26 1915

Referred to Mr. Mauns.

AWZ

1.4.15

AMER
RECEIVED
LONDON

© 2021

Lloyd's Register
Foundation

In damage cases a
declined?

REPAIRS, OR E

Th

ings, built

the work in

ed 3rd Dece

Dr

ne and pro

the outer

The hull p

located ou

Th

MARKET OF DAMA

Removed

Removed and Pa

Faird or Repairs

ESSENT CONDITION

ks

iling of Decks

erways

nings

ns & Fastenings

nde Plating

ling of ditto

g

stbocks & Oracles

homs

nes

ree Framen

ns

ons

General O

State of
this survey, di
survey, 1,1,1,

Fee (per Deck

Damage or Rep

ing Expenses (H

Surveyor's Fee