

R. S. TAYLOR,
SURVEYOR,
ASSOCIATE INST. NAVAL ARCHITECTS.
TELEPHONES: OFFICE No. 602
PRIV. RES. No. 1045
CABLE ADDRESS:
"SURVEYOR."
CODES:
SCOTT'S, A.B.C. AND STANDARD.

Lloyd's Register of British & Foreign Shipping,

LLOYD'S REGISTER,
LONDON, EAGLE STREET.

RST/REC 8 MAR 1915 *Brisbane,* 23rd January 1915

ANSO

Sir,

S. S. "BINGERA"

In mine of the 30th December I attributed to the irregularity of the Mails, my inability to forward at that time a full report, I don't know why I said that, for I meant to say that owing to matters beyond my control I was not able to then send the full report.

As stated I inspected the vessel from time to time, she docked at the end of July for the purpose of changing stern washes, propeller shafts, etc. and the work was only completed and the vessel in commission in early December (4th) and whilst I had the freedom of inspection I had no authority to go into the boilers, nor the right to ask Mr. Evans or anyone else to do so, and now Mr. Evans is away in Camp I am endeavouring to get a report from the Chief Engineer Surveyor to the Marine Board, but he too has been on leave, and thus I have not been able to complete the report; meantime the steamer is running very satisfactorily.

I am, Sir,

Your Obedient Servant,

R. S. Taylor
Surveyor.

Scott, Esq.,

Secretary,

LONDON. E.C.



© 2021

Lloyd's Register
Foundation

Tomoko K. K.

MAR 8 1915

11.3.15 JIM

VIOLATION PAGE 2

RECEIVED
JAN 10 1962
U.S. DEPARTMENT OF AGRICULTURE
WASHINGTON, D.C.

Lloyd's Register
Foundation

TELEPHONES (OFFICE NO. 1)
TELEGRAPHIC ADDRESS: 80
CODES: 1. SCOTT'S, A.B.C. AND