

they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Occasional Slipping Survey on 29th April and sub

HULL (OUTSIDE). This was thoroughly cleaned and examination and

3m.24.

POSTPONED SURVEYS.

Case of the Steel S.S. "NGAHERE"
No. 28506 in Reg. Bk. 1090/556 tons, Built 1908-8
Classed 10007 Owners Mann, George & Co
4.23 T. 3.21 a Port of Registry Port Glasgow
J. N. 3-3.21 Thine 3.21
R. 4.23
Survey Due Screwshaft survey due 3.24.
Eciler Survey due 4.24.

The Owners state the matter of the above surveys
has their attention.

Submitted advice deferred

Ans.
14.4.24.

Committee's Minute

Decision

TUE. 15 APR. 1924

Deferred
W



© 2021

Lloyd's Register
Foundation

Character Assigned Not for