

total capacity tons. FPT tons; APT tons; MT feet tons.

precisely as in Re

Only alterations in the existing records of tanks should be inserted.

CHARACTER.
X for Special Survey.
Date of last Survey and of

Subject to indicated plating in way of No 1 hold (S.S.)
being dealt with at Owners convenience.

11

Chief Ship Surveyor

Received from Chief Ship Surveyor

27 FEB 1941

NAME

"Persens"

Rpt.

P. N.

No. 3279

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey

The Port Hatch (Aching) Surveyors reports this vessel placed in dry dock, bottom cleaned and coated, ~~repairs or renewals to~~ and minor repairs effected.

Indicated plating, as above, not dealt with.

It is submitted the vessel appears worthy to remain as classed with record of survey 12.40 as recommended, subject as above.

100 A1
12.40 P. N. } subject to.

PLATING to be DRILLED when vessel is 24 years old, or at next Special Survey thereafter.



25.2.41
© 2020

Lloyd's Register
Foundation

W71-0227

Side Firing

in way of sidelights

Windlass

Hatches

Have pumps been examined and found effi-

Condition,
(State
Equipment