



DECEMBER 30th, 1921.

3m.8.21.

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME SS Monte Enappa Report Phl No. 4794

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey Damage When due \_\_\_\_\_

Vessel to be placed in dry dock for further examination at the first convenient opportunity.

*M*  
*MEI*  
27.1.22



© 2020

W710-0102

Lloyd's Register Foundation

Surveyor to Lloyd's Register.

Food Vessel  
(...)  
th  
ained  
removed)  
e ranged)  
Rigging

Book consequent  
nd to have rec

ble in  
ith fre  
placed  
icent opportunitie

*House*