

2m.11.20.

3 FEB. 1922

1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

M. S. "Coyt"

Rpt.

Kon

No.

135
140

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through

Heavy Weather

now repaired as follows:-

| | Plates | Frames | R. Frames | Floors | Beams | Str. Plates | Dk. Plates |
|--|--------|--------|-----------|--------|-------|-------------|------------|
| Renewed | | | | | | | |
| Removed and faired or repaired..... | | | | | | | |
| Faired or repaired in place..... | | | | | | | |

~~Other items:-~~

Vessel Examined afloat welding orhaulers
and repairs effected, by electric welding, to
gunset angles in Nos. 2 & 5 tanks and deck
bar on underside of No. 2 tank.


It is submitted the vessel is worthy to remain as classed with

record of Survey

as recommended

subject to the repairs
effected by electric welding being specially examined
at next dry docking.

As now, Sub. to
etc.



© 2020

1. 2. 11

Lloyd's Register
Foundation