

Less above Crown of  
 Engine Room ... }  
 FOR FEES... }  
 ne Room

20.14  
2714.12  
 900.34  
 20 31

2nd Number ..... 26976  
 Proportions—Breadth to Length ..... 6.82  
 Depth to Length ..... 12.90

Managers .....  
 (Where necessary to be entered in Reg. Book.)  
 Residence Newcastle  
 1

Time of Receipt 10/40

**LLOYDS REGISTER**  
**LONDON,**  
**REOR 23 NOV. 1906**  
**ANSR 73**

**TELEGRAM.**

**POST OFFICE TELEGRAPHS.**



If the Receiver of an Inland Telegram doubts its accuracy, he may have it repeated on payment of half the amount originally paid for its transmission, any fraction of 1d. less than 1/2d. being reckoned as 1/2d.; and if it be found that there was any error, the amount paid for repetition will be refunded. Special conditions are applicable to the repetition of Foreign Telegrams.



Charges } £ s. d.  
 to pay }

W. Kettlepool at 10/75a .M., Received here at 10.33 .M.

Committee Lan  
 Ben Leonard fees paid  
 Surveyors.

N.B.—This Form must accompany any inquiry made respecting this Telegram.



© 2020

Lloyd's Register  
 Foundation

Average space	40	-	-	40	-	-	Deck, material and thickness	
RS, In 'tween Deck, size and spacing	23x	40	-	23x	40	-	Bridge Deck Stringer Plate, br'dth & thickness	50
Hold	44x	40	-	44x	40	-	Angle on ditto	45°

Referred to the Chief Ship Surveyor,  
and the Chief Engineer Surveyor.

*ad.*  
Referred to Mr. Twinn,  
Referred to Mr. Wood.

*W. S. G. H.*

NOV 23 1906

*Noted by Lt. B. H. B.*



© 2020

Lloyd's Register  
Foundation