

577
No. 12, 11.

1

Sent to Chief Surveyors 1. 5. 18.

Received from Chief Surveyors 1 MAY 1918

VESSEL'S NAME Wm. Rockefeller Report J.H.L. No. 2588.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey Equipment under the endorsed rule.

The modified rules require the total length of chain cables at present to be 240 fathoms in length.



© 2021

1. 5. 18.

Lloyd's Register
Foundation

W714-0076