

ived by Chief Ship Surveyor 3. 9. 01

Received from Chief Ship Surveyor _____

SEL'S NAME See. S.S. "Whitgift" Report hwc. No. 42278

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ture of Survey _____

Exist entry


It is submitted that before this case receives the consideration of the Committee, the Builders should be informed with regard to the omission of the ceiling from the top of the inner bottom of this vessel that it will be necessary for the written consent of the Owners to be produced before the vessel can be recommended to the Committee for Classification in the Society's Register Book.

J.F.L. C.H.P.
3/9/01

The Surveyors should be requested to state the number of water-tight bulkheads which have been fitted in the vessel, as this has been omitted from their report, and they should at the same time state whether ~~it web frames have been fitted forward as shown the approved pro~~

C.H.P.

Dr hwc 3. 9. 01



© 2020

W715-00215

Lloyd's Register
Foundation