

3m.8.21.

1

Sent to Chief Surveyors

6-22

Received from Chief Surveyors

6-22

VESSEL'S NAME

Sheelss Kerkyra

Report

Liap

No.

2066

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

It is submitted the wires be informed  
the chain cable required in this case  
should be  $1\frac{7}{8}$  in diameter.

See Over 6/2/22

M

6-2-22



© 2021

Lloyd's Register  
Foundation