



**GENERAL REMARKS** (State quality of workmanship, opinions as to class, &c.)

This boiler has been constructed under Special Survey the materials and workmanship are good & efficient and when tested with hydraulic pressure was found tight & satisfactory.

This boiler has been fitted on board in accordance with the Rules. The safety valves have been adjusted under steam and blew off freely at 90 lbs per sq. pressure -

H. P. Cornish

Certificate (if required) to be sent to

The Surveyors are requested not to write on or below the space for Committee's Minute.

The amount of Entry Fee...	£	:	:	When applied for,
Special ... ..	£	:	:	19
Donkey Boiler Fee ...	£	2	2 0	When received,
Travelling Expenses (if any) £	:	:	:	19

*Donkey  
Boiler  
Paid 11.3.07.*

*Geo. A. Milner & H. P. Cornish*  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

FRI. APR 19 1907

Assigned

*See Minute on Rec. Rpt.  
No 52639*



© 2021  
Lloyd's Register  
Foundation