

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 17/2/10 When handed in at Local Office 17/2/10 Port of Glasgow

No. in Reg. Book 30 Survey held at Glasgow Date, First Survey 14th Feb. Last Survey 15th Feb 1910

30 *Suppl* on the Wood, Iron or Steel T S S "Kangalira" Master

TONNAGE:— Built at Belfast By whom Workman Clark & Co. L^{td} When

GROSS 6991 Owners Shaw Sanell & Albion L^{td} Port belonging to Southampton

UNDER DK. Owners' Address (if not already recorded in Appendix to Register Book)

NET Surveyed Afloat or in Dry Dock? Afloat Name of Dock Princes Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

total capacity tons. FPT tons; APT tons; MT feet tons. } 100 A.I. Shells etc Class Contemplated

S.B.—All alterations in the existing records should be underlined. If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port Society's Freeboard (if assigned) as painted on Ship and now verified

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion 1st Entry

The collinsons scuppers on Shelter Deck have been tested with water and found in efficient condition
The Watertight doors in bunker sockets have been examined & tested

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Fell.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt (state which.)	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder	Caulking ditto	Sails
Rivets	Steering gear and its connections	Treenails ditto	Equipment letter
Breasthooks & Crutches	Windlass	Breasthooks & Stemson ditto	Anchors, No. of
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (state if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	" length size
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	" Rule length size
Floors		Stringers, Clamps & Shelves ditto	(per Table 22)
Keelsons		Salting ditto	Hawser & Warps
		(State if examined.)	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c. :—


State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,09," or "to remain as classed and to have record of survey, 1,09, and the notations of ss No. 1-09 and pEND09, &c."

The above is for the information of the Committee

Survey Fee (per Section 28)	£	Fees applied for,	19
Special Damage or Repair Fee (if any)	£	Received by me,	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

J. A. Mackellar
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Character Assigned
TUES. 22 FEB 1910
see minute on 2^o report



W720-0049

If no. in the Report sent home, or if the Report is not sent home, it will be sent to the Registrar.

No Certificate required if no. to be sent to