

LLOYD'S REGISTER OF SHIPPING, LLOYD'S REGISTER  
NEW YORK

454, CALIFORNIA STREET,

REC'D JUN 25 1917

ANS'D

*send for*  
*6/26/17.*

SAN FRANCISCO

19th June

1917.

Dear Sir,

In reference to steamer "WAR KNIGHT",  
Sfo. Report No.2525 please note that the thickness of floors  
in cellular double bottom should read .52 under boilers,  
and not under Engines, as indicated in first entry report.  
I regret this clerical error in the preparation of report.

Yours very truly,

*Arnold Bennett*

The Secretary,

NEW YORK.

AB-HJ

*Rpt. forwarded to Lou.*



© 2020

Lloyd's Register  
Foundation

*W72-018*



Referred to the Chief Ship Surveyor

7876

SAV FRANCISCO

424 CALIFORNIA STREET

THE REGISTER OF SHIPPING, LLOYD'S REGISTER



© 2020

Lloyd's Register  
Foundation