

M.M. 828

1

2.16

Received by Chief Ship Surveyor 21-11-14

Received from Chief Ship Surveyor 21 NOV 1917

VESSEL'S NAME Steer S.S. "Lightfoot"

Rpt. Sld. No. 24095

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Signature of Surveyor DAMAGE.

Damage through Grounding


now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items: Vessel examined on Pontoon, bottom cleaned & coated, top riveting of stern frame renewed as necessary. No bottom damage sustained.

It is submitted the vessel is worthy to remain as classed with record of Survey 11-14 as recommended

100 A.I.  
11-14 SLD.



© 2005  
Lloyd's Register  
Foundation  
W 721-0175