

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 4/6/08 Port of GRIMSBY

No. in Reg. Book 157 Survey held at Grimsbly Date, First Survey 28. 5. Last Survey 2. 6. 1908
(No. of Visits Three) Master Sc. K. Washington

TONNAGE:-
GROSS 264 Built at Selby By whom Bochmans & Sons When 1907
UNDER DE. 232 Owners Premier P.F. Co. Ltd Port belonging to Grimsbly
NET 131 Owners' Address (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? 30h. Name of Dock 30h. Destined Voyage Fishing

WB=CeILDBoRDBa feet; uE&B feet; f feet; }
total capacity tons: FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 5309 Port Gms.
CHARACTER: * for Special Survey. Date of last Survey and of Periodical Surveys. Year Assigned expired. Machinery and Boiler Surveys (including date of N.B., if any).
1-100A1 Stm. Tranker 4107. L.M.C. 407.
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey:

The bottom trudders cleaned, examined recoated.

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESSENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks <u>good</u>	Inner Bottom Plating	Engine Room Skylights <u>good</u>	(State if on Felt.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats <u>good</u>
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained <u>from dx</u>
Outside Plating <u>good</u>	Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder <u>good</u>	Caulking ditto	Sails <u>good</u>
Rivets	Windlass	Treenails ditto	Equipment letter
Breasthooks & Crutches	Have Pumps now been examined and found efficient? <u>no</u>	Breasthooks & Stems ditto	Anchors, No. of <u>3</u>
Transoms	Have Sluice Valves now been examined and found efficient? <u>no</u>	Transoms, Pointers, & Crutches ditto	Cables (State if new ranged) <u>no</u>
Frames	Have Watertight Doors now been examined and found efficient? <u>no</u>	Timbers of Frame at openings ditto	" length (on board) size
Reverse Frames		Ditto ditto at other places ditto	" Rule length (per Table 22) size
Floors		Stringers, Clamps & Shelves ditto	Hawsers & Warps <u>good</u>
Keelsons		Salting ditto (State if examined.)	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptd98, &c."

This vessel is eligible in my opinion to remain as classed with fresh records of 6.08

Office Fee (if chargeable) per Scale II, Sec. 27	Fees applied for,
Survey Fee (per Section 25)	19
Special Damage or Repair Fee (if any) (per Sec. 25.)	Received by me,
Travelling Expenses (if chargeable)	19
Second Surveyor's Fee (if any)	

C. Martell
Surveyor to Lloyd's Register of British & Foreign Shipping.



Committee's Minute WED 10 JUN 1908
Character Assigned 100091
Stm Tranker

Has a Survey also been held on the Machinery of the Ship? If so, to the Report sent now, or when will it be sent?

Is Certificate required? If so to be sent to