

Surveyors

21.8.17

Received from Chief Surveyors

ME

Shells "War March"

Report

No. 2547

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

by

When due

100A-1 (Steel) Shells Deck with freeboard
2 LK (Steel) x Shells SK (Steel) x Webframes. Longitudinal Framing
Cell DB 355 1306 C. M.T. 25' 7986 D.T. a 30 2286. F.P.T. 806

A.P.T. 1756

FK. 7BH. pl. asp. arcp.

M
21.8.17

It is concluded ^{cap} plates are fitted
in the Shells between decks ^{sub} 9th Surveyors
shows state of this ^{so} ^W

M

27/8/17



© 2021

Lloyd's Register
Foundation