

REPAIRS, OR EXAMINATION AS PER RULE, FOR

W726-0103

201.18

1

Sent to Chief Surveyors

21. 10. 18

Received from Chief Surveyors

VESSEL'S NAME

St. St. Moorgate

Report

Liv

No.

78263

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.

Nature of Survey

Re-installment  
Damage

When due



100 A. 1.

10 18 Liv.

As Liv No. 3-10, 18

LEN. 18

Cell DBa 117' 4 E+B 42' f 171' 1009t. FRT 616 APT bot.

P23' B119' E31'

Lloyd's a 16 P



© 2020  
Lloyd's Register  
Foundation

The Certificate of Classification, to be endorsed  
"Cargo battens not fitted," and the same  
notation to be printed in the Register Book

General Observations, Opinion as to Class, Recommendation, &c.:—

Standing & Running Rigg