

S.S. " THE PRESIDENT", building by The Ailsa Shipbuilding Co. (N^o 128)

Equipment No. 10628, letter "i" (old table).

The Glasgow Surveyors state the following bower anchors have been delivered in the Yard for this vessel, viz:-

			cwts.,	qrs.,	lbs.
1st bower anchor, stockless, weight	15.	3.	7.		
2nd " " " "	13.	2.	7.		
3rd " " " "	13.	1.	21.		
Collective weight	42.	3.	7.		

The following anchors are required by Table 22, viz:-

			cwts.,	qrs.,	lbs.
1st bower anchor, stockless, weight	15.	0.	0.		
2nd " " " "	15.	0.	0.		
3rd " " " "	12.	3.	0.		
Collective weight	42.	3.	0.		

The 2nd anchor is 1 cwt., 1 qr., 21 lbs., less in weight than required, but the weight of the 1st and 3rd anchors and the collective weight of the three anchors are 3 qrs., 7 lbs.; 21 qrs., 21 lbs.; and 7 lbs., respectively greater than required.

The Owners state they have no objection to these anchors if they comply with the Committee's requirements in all ways.

It is submitted that as the weight of the 1st and 3rd anchors and the collective weight of the three anchors are in excess of the requirements of Table 22, the anchors might be approved for the figure 1.

TUES. 4 OCT 1904

Approved

Lloyd's Register
Foundation
S. H. P.
16/10/04

The attached letters should be returned to the Surveyors.

(4th No Reference)
Ans: 3-10-04
Ans: 4-11