

Rot Report n<sup>o</sup> 5270 <sup>5</sup>


S. tug "Thames"

Before dealing with this case it  
is submitted that the Rot  
Surveyors should be requested  
to state from what vessel  
the engines now fitted to the  
above vessel had been removed.  
From

JHC 19-6-07

L.S.  
19.6.07

Ln Rot: - 19/6/07



© 2021

Lloyd's Register  
Foundation