

rudder cleaned examined and recast

Rudder unshipped to rime rudder

is fitted
is by class

by Chief Ship Surveyor 27. 9. 19

Received from Chief Ship Surveyor 30 SEP 1919

EL'S NAME Stl. S.S. "THAMES". Rpt. Rot. No. 10948a

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

The Rotterdam Surveyors report this vessel has been placed in dry dock, the bottom cleaned & coated & rudder pintles renewed.

The main piece of the rudder which was found to be more or less grooved at the arms, have been repaired by electric welding to prevent further corrosion.

It is submitted the vessel appears worthy to remain as classed, with record of survey 9. 19, subject to the main piece of the rudder, where repaired by electric welding, being specially examined at the next dry docking.

100A-1. } subject
9.19 Rot }

© 2021
29. 9. 19
W727-0120
Lloyd's Register
Foundation

Wood Vessels.....	
alt.)	
length.....	Y
rod	
not es	
retained	
removed)	
G	
Comple	
re ranged)	
size	
size	
food	
Rigging.....	

book consequent u
nd to have recor