

SS "TEESBOROUGH".

N.B. The following is an extract from the report of the survey held by the Newcastle Surveyors in August last:

L "It is stated that the tail shaft (C.L.) has been drawn and the lower half of bush rewooded. No opportunity was given to examine this work, the Owners Superintendent informing the repairers it was not necessary for the shaft to be examined at this time, being drawn for rewooding of bush. Work completed at night". X

Submitted action be deferred for 3  
months.

En S.  
24. 2. 16.



© 2021

Lloyd's Register  
W 728-0172  
Foundation