

The greater part of the 2nd SS No. 1, dur 1,40, has been held.

11

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME _____

PORT BRISBANE

Rpt. _____

Syd.

No. 17931

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

The Sydney N.S.W. Surveyors report this vessel placed in dry dock, bottom cleaned and coated, repairs to and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey as recommended.

✓ action to be deferred.



© 2019

Lloyd's Register
Foundation

W73-0060