

W431-0001

3

Received by Chief Ship Surveyor *20/7/09*

Received from Chief Ship Surveyor

VESSEL'S NAME *St. Es. Yew*

Rpt. *Sub* No. *2870*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey S.S. No. *1* AND DAMAGE.

Damage through *grounding & collision*
 now repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	<i>3</i>						
Removed and faired or repaired.....	<i>6</i>						
Faired or repaired in place.....	<i>21</i>						<i>1</i>

Other items:- *the sole piece of the stem frame and a few ribs removed, the rudder & a few frames & were frames repaired & minor repairs*

The S.S. No. *1* has also been held and following repairs done due to wear and tear:- *minor repairs*

It is submitted the vessel is worthy to remain classed

with record of Survey *7.09* and notation of

St. Es. Yew as recommended.

10071
7.09 Sub
22 Sub No. 1-09

© 2021 Lloyd's Register Foundation
 28/7/1909