

28 DEC 1916

1m, 7, 16.

Received by Chief Ship Surveyor 27.12.16

Received from Chief Ship Surveyor

VESSEL'S NAME *Sheels Janoir*Rpt. *Live* No. *69437*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey S.S. No. *2* AND DAMAGE.Damage through *stranding* see *London report no 78132*
CF 38322

now repaired as follows:-


	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	16			2			
Removed and faired or repaired.....	44	18		3			
Faired or repaired in place.....	35	35		20			

Other items:- *Vessel examined in dry dock, Tank interstals*
repaired as required & minor repairs carried out.

The / S.S. No. *2* has also been held and following repairs done
due to wear and tear:- *Bottom cleaned & coated 10 floors &*
12 interstals repaired deck under dunkey biler part
renewed & minor repairs carried out.

It is submitted the vessel is worthy to remain classed with record
of Survey 11.16 and notation of *as she is 2-16*
as recommended. *without special condition*

100A.1.

11.16 *she**as she is 2-16*

© 2021

Lloyd's Register
Foundation

W731-0092