

Rpt. 8.

(Received at London Office)

WRECK BOX  
No. 46 Top

No. 142359

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

19

When handed in at Local Office

19

Port of

Callao

No. in  
Reg. Book.

Survey held at

Date, First Survey

Last Survey

19

on the Wood, Iron or Steel

Twin Lc. "Balcatta"

(No. of Visits)

Master E. Boddart

TONNAGE:-

GROSS

3109

UNDER DECK

2301

NET

2482

Built at

Seattle, Wash.

By whom

Patterson & Macdonald when 1919

Owners

Philberg line (J. E. Philberg mgr)

Port belonging to Seattle

Owners' Address

(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

feet; f

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No.

3403 Port S Fo

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.  
For Special Survey.  
Date of last Survey and of  
Periodical Surveys.

+12 A.1.

6,20

Salted.

Years  
Assigned  
expired.

Machinery and Boiler  
Surveys  
(including date of N.B., if any).

+L m c m, 9

OLD ENGINE

Society's Freeboard (if assigned) as  
painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

## SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

## PRESENT CONDITION OF THE

Decks	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Caulking of Decks	Inner Bottom Plating	Engine Room Skylights	When put on, Month Year
Waterways	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Boats
Coamings	State if Tanks now tested	Scuppers	Masts, Yards, &c.
Beams & Fastenings	Bulkheads	Cargo Hatchways	Condition, how ascertained
Outside Plating	Ceiling	Hatches	(State if wedges removed)
Caulking of ditto	Cement or Asphalt (State which.)	Planking of Wood Vessels	Sails
Rivets	Rudder	Caulking ditto	Equipment letter
Breasthooks & Crutches	Steering gear and its connections	Treenails ditto	Anchors, No. of
Transoms	Windlass	Breasthooks & Stemson ditto	Cables (State if now rigged)
Frames	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	„ length size
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	„ Rule length size
Floors	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Hawser & Wops
Keelsons		Stringers, Clamps & Shells ditto	Standing & running Rigging
		Salting ditto	
		(State if examined.)	

## General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Survey Fee (per Section 29) £

Special Damage or Repair Fee (if any) (per Sec. 29) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

10

Received by me,

10

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

FRI. 18 FEB. 1921

Character Assigned

Write La 18/2/21

Wp

Deferred for dry docking

TUE. APR. 26 1921



Lloyd's Register  
Foundation

W734-0208