





Drinks connecting frames to brackets.

In way of No 1 plates on 3<sup>rd</sup> & 4<sup>th</sup> strakes below main

Inside of Fox Peak Tank. the frames spaces Part 8  
Stark have been filled in with wood & painted over  
and shored off. from Centre division plate. to counter  
act ice pressure. Permanent repairs have had to be deferred  
owing to vessel being urgently required & also to scarcity of labour.  
Part SS N<sup>o</sup> 2 advanced.

Bunkers cleaned & examined. Ceiling and  
lumber boards lifted and E. R. Tank tested. Bunkers  
scaled & coated. 2. Stiffening angle Bars on casing  
Port & Starb. - renewed together with 2. Brackets latrine  
stays. & New coaming fitted to Centre Hatch. Port side.

## ANCHORS.

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]

W. Burn.