

F.E.

Received by Chief Ship Surveyor 12.1.07

Received from Chief Ship Surveyor

VESSEL'S NAME *St. Steam Trawler "Margaret"* Rpt. *Full* No. *18656*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>8/16" in lieu of 8/20"</i>	<i>Not required</i>
Spar Sheerstrake . .		
Description of Framing:— <i>Ordinary, increased to compensate (viz., ordinary, deep, zed, channel or bulb-angle) for omission of reverse frames.</i>		

The 2nd. anchor is 7-21 lbs. less in weight than required, but the 1st and 3rd anchors are 2 lbs. and 3 lbs. respectively in excess.

In other respects This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A 1 ("Steel") *"Steam Trawler"* as recommended.

∇ 100 A 1 ("Steel") *"Steam Trawler"*
18R.

BK 7 1/2" 38H Can. Lloyd's A&CP Q80' F23'

BEAMS, 1

Plat
Angle
Spacing

PILLARS, In 'two

" Hold
" Quarter, 'in

WEB FRAMES, In Fore Body, No. and Spacing

" " " Brdth. & Thickness

No. of Side Stringers

" Deck, Material and thickness *P.P.m.*

* If Iron or Steel Deck, state if whole or part, and if wood

Number.

STIFFEN



C.H. J.
© 2020

Lloyd's Register
Foundation

W744-0069