

W744-0147

1

Received by Chief Ship Surveyor *15.4.10*

Received from Chief Ship Surveyor

VESSIL'S NAME *Shed SS. Umballa* Rpt. *Imo* No. *6516*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through *Collision*

now repaired as follows:-

| | Plates | Frames | R. Frames | Floors | Beams | Str. Plates | Dk. Plates |
|-------------------------------------|--------|--------|-----------|--------|-------|-------------|------------|
| Renewed | 1 | - | - | - | - | - | - |
| Removed and faired or repaired..... | 1 | - | - | - | - | - | - |
| Fired or repaired in place..... | - | 2 | - | - | 1 | 1 | - |

Other items:-

Vessel examined in dry dock, bottom & rudder cleaned & coated. Bulwarks repaired & other minor repairs carried out.

The SS has become due at the end of this month. The Surveyors state it will be held before the expiration of the year of grace.

It is *the* *submitted* the vessel *is* *worthy* to remain as *classified* with

record of Survey *4.10* as recommended

100 A-1 Steam Trawler

4.10 Imo

Opinion

and, if so, what alterations to be recommended and to have recorded

eligible
sh record of



of the vessel in the Register Book
 Survey, "to remain as classed and
 main as cla
 Lloyd's Register
 Foundation

for taking or below the space for Committee's Minute.