

12 MAR 1918

Received by Chief Ship Surveyor

11.3.18

Received from Chief Ship Surveyor

VESSEL'S NAME

St. J. S. Upcerne

Rpt.

Moc.

No.

70743

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

Condition

Damage

The class of this vessel is subject to one poop side plate being repaired at Owners convenience.

The Newcastle Surveyors now report the vessel has been placed in dry dock the bottom cleaned & coated.

The poop side plate referred to above has not been dealt with at this time.

It is submitted the vessel appears worthy to remain as classed with fresh record of Survey, Subject as above.

100 A.I.

3.18

Moc.

Subj. to

11.3.18



© 2019

Lloyd's Register Foundation

W745-0001