

Received by Chief Ship Surveyor 12-5-15.

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "URBINO" Rpt. Hull No. 28484

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor

It is submitted that before this case receives consideration this report and approved profile should be returned to the Surveyors who should be requested to state clearly whether the bulkhead on frame No.99 has been extended to the upper deck or whether this bulkhead has been stopped at the 2nd deck and a web frame or partial bulkhead fitted <sup>in</sup> ~~to~~ the <sup>tween</sup> ~~lower~~ decks as shown on the plan.

A letter from the Owners agreeing to the omission of the bulkhead in tween decks should be forwarded if the latter arrangement has been adopted.

The Surveyors should also be requested to state whether independent means of steering have been provided as required by paragraph 3 Section 43 of the Rules.

*Cr. B.S. 15  
aptd to plan*

*Per Mr. [unclear]  
15-5-15  
TW*

*[Signature]*

13-5-15.



© 2019

Lloyd's Register Foundation

W745-0110