

of Ship Surveyor 22. 4. 20

Received from Chief Ship Surveyor 24 APR 1920

NAME Wood S.S. "WAR CASCO".

Rpt. Gib.

No. 1423

Notes of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/22.

Key

The Gibraltar Surveyor reports (27th February) damage through straining when loading iron ore. Part of the cargo was discharged, the vessel examined in dry dock, and the following repairs effected:— Butts & seams of outside planking recaulked, fastenings overhauled, and some additional stiffening fitted.

The vessel was undocked, and when partly reloaded, found to be badly on fire. She was towed out of Admiralty waters, subsequently went ashore, burnt out to the water edge, and became a constructive total loss.

In the circumstances, no action is necessary on this report.



© 2019

23. 4. 20

Lloyd's Register Foundation

W745-0136

defects

broken.