

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 22/8/14 When handed in at Local Office 14 Port of GRIMSBY  
No. in Reg. Book. 2 Survey held at GRIMSBY Date, First Survey and Last Survey 30/7/1914  
on the Wood, Iron or Steel S.S. "XERXES" Master

TONNAGE: Built at Selby By whom Cochrane & Sons When 1908 5  
GROSS 243 Owners Buckworth & Mumby Ltd Port belonging to Swansea  
UNDER DECK 216 Owners' Address (Grimby Mgr)  
NET 96 (if not already recorded in Appendix to Register Book).

Surveyed in Dry Dock? Name of Dock Fish Dock Destined Voyage Fishing  
WB=CellDBorDBa feet; u&B feet; f feet; Particulars of Classification (which must be inserted  
total capacity tons. FPT tons; APT tons; MT feet tons. precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.  
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 9258 Port Gms.

CHARACTER.	Machinery and Boiler
For Special Survey, Date of last Survey and of Periodical Surveys.	Surveys (including date of N.B., if any).
1-100A1	L.M.C.
Stm Brawler	4.12
12-13	
S.S. SWS No 1-12	8.2-13.
Society's Freeboard (if assigned) as painted on Ship and now verified	

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking:

The vessel placed in dry dock and the bottom and rudder cleaned, examined, and recoated. Three rudder plates renewed.

SUMMARY OF DAMAGE REPAIRS :—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—			
Renewed ... ..												
Removed and Faired or Repaired ... ..												
Faired or Repaired in place ... ..												
PRESENT CONDITION OF THE							Dblg. Plates under Sounding Pipes.			Copper, or Y.M. of Wood Vessels		
Decks							Engine Room Skylights			(State if on Port.)		
Caulking of Decks							Coal-Bunkers, Open'gs, Lids, &c.			When put on, Month		
Waterways							Scuppers			Year		
Coamings							Cargo Hatchways			Boats		
Beams & Fastenings							Hatches			Masts, Yards, &c.		
Outside Plating							Planking of Wood Vessels			Condition, how ascertained		
Caulking of ditto							Caulking ditto			(State if wedges removed)		
Rivets							Treenails ditto			Sails		
Breasthooks & Crutches							Breasthooks & Stemson ditto			Equipment letter		
Transoms							Transoms, Pointers, & Crutches ditto			Anchors, No. of		
Frames							Timbers of Frame at openings ditto			Cables (State if now ranged)		
Reverse Frames							Ditto ditto at other places ditto			length size		
Floors							Stringers, Clamps & Shells ditto			(on board)		
Keelsons		Seking ditto			Rule length size							
		(State if examined.)			Hawser & Warps							
					Standing & Running Rigging							

General Observations, Opinion as to Class, Recommendation, &c.:—  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and ptnd11, &c."  
This vessel is eligible in my opinion to remain as classed with fresh records of 7.14.

Survey Fee (per Section 22)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 22)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute TUE. AUG. 25. 1914  
Character Assigned 100A1 Stm Brawler B.S. 114