

to Chief Surveyors 15-1-17

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "Tartary" Report Liv. No. 41313

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey Repairs & examination of temporary repairs ~~which~~ previously effected (B.O. r.p. to 5461 & 5584).
(2nd S.S. no. 1 due 8.17 & p.tly. held)

Notes

Vessel to be dry docked and 2nd S.S. no. 1 completed on return from present intended voyage.

Permanent repairs to be effected to stem plating at the first available opportunity.



© 2021

Lloyd's Register
Foundation

W751-0006