

Urgent

S.S. Stock Force *Bow rpt. 1215*

S.S.No.186 building by Messrs R.Williamson & Sons,Workington.

Equipment No.9298,letter "h" new Table 22.

Messrs S.Taylor & Sons state they have made the following
bower anchors for this vessel,viz;-

	cwts.,	qrs.,	lbs.
1st bower anchor,stockless	12.	2.	14.
2nd " " "	12.	2.	0.
3rd " " "	10.	1.	20.
Collective weight	35.	2.	6.

The bower anchors required by Table 22 are as follows;-

	cwts.,	qrs.,	lbs.
1st bower anchor,stockless	12.	2.	0.
2nd " " "	12.	2.	0.
3rd " " "	10.	2.	0.
Collective weight	35.	2.	0.

It will be observed that the 3rd bower anchor is 8 lbs.,
less in weight than required,but the collective weight of the
three bower anchors is 6 lbs.,in excess.

It is submitted,in view of the slight deficiency in weight
of the 3rd bower anchor,that the same might be approved for the
figure 1.

FRI. 3 MAR 1905

Approved



L.H.T.
© 2021 *3/3/05.*

Lloyd's Register
Foundation

Fr. 2-3.05
Inv. 3rd
Plans

W. S. Taylor & Sons

" in Hold
S, in Fore Body, No and Spacing

Large Brackets.

" Tie Plates
" Deck, Material and thickness *Steel*