

F. E.

Rpt. *Hpl.* No. 13100

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/32.*)

CLASSIFICATION.		
Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	$\frac{1}{20}$ " less, but compensated by increased thickness of strake above.	Proportions
Spar Sheerstrake . .	$\frac{2}{20}$ "	
Description of Framing:— Deep (Bulb angle) framing, increased in (viz., ordinary, deep, zed, channel or bulb-angle). account of erections.		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100 A 1 ("Steel") *"Spar Deck"* as recommended.

† 100 A 1 ("Steel") "Spar Deck".

1 DR (Set) & spar DR (pt Lm & pt Ste) & deep framing.

N. Bx Cell DB a 4 u E 136' f 152' 8986 APT 390

FK 6BH Cem. Lloyd's A x CP P27' B96' F34'

© 2021

Lloyd's Register
Foundation

W751-0122

PILLARS, IN TWELVE BOOKS, BY

Hold

~~Quarter, 'tween Dks..~~

in Hold

WEB FRAMES In Every Body No. 1

Deck. Material and thickness.

Forecastle Deck Stringer Plate, b'dth & th'kns

„ Angle on ditto

Tie Plates