

In damage cases where the Surveyor has not made a special damage report, he is not
declined? *not asked* Was a damage report made by anyone else? If so, by whom?

Lloyd's Register

Did the Surveyor personally go inside each Main Boiler separately and make a thorough

WA35-0143

of "Spiral."

Appl. Rpt 15169.

This vessel was built in 1906 but not under the Survey of this Society's Surveyor.

A survey has now been held with a view of its classification with this Society, & satisfactorily reported, the engines & boilers have been examined & found to comply with the requirements of the Rules. & are in good working condition -

It is submitted that
this vessel is eligible for
THE RECORD L.M.C. 10.15.

NS 10.15. 180^{lb}. 80^{lb}. (S) 160 NHF.
25B. 4c.f. 6580. HS 2712.



© 2020

Lloyd's Register
Foundation

Auxiliary Engines Similarly sent to Shop &