

st Report, No.

Port

ONE: NAT. No. 648.



Lloyd's Register of British & Foreign Shipping,

Royal Exchange,

Middlesbrough, 8th October, 1907.

The Secretary,
LONDON.

sir,

LLOYDS REGISTER,
LONDON.

REC'D 9 OCT 1907

ANS'D

I have to inform you that the new steamer "SNOWDONIAN", Messrs. Richardson Duck & Co's S.S. No.588, received slight damage to bottom plating on portside while launching. The intention was to dock the vessel on the Tyne to effect the necessary repairs, but as the Owners are anxious to have the vessel as early as possible to save a charter, it has been proposed, with the Owners consent, to effect a temporary repair afloat, on the understanding that the vessel will be drydocked for permanent repairs after this voyage.

Examination shows plate slightly indented, a few seam rivets and caulking in way of same started, and in our opinion satisfactory temporary repairs can be effected.

The Builders are anxious to know if this proposal will effect the Classification and issue of certificates.

Please wire reply to this office.

I am, Sir,

Your obedient servant,

W.H. Cooper

© 2020

Lloyd's Register
Foundation

Referred to the Chief Ship Surveyor.

OCT -9 1907

Wire requested
+ Mr. Magne's note

It is submitted that the Middlesbrough
Surveyor's recommendation in this case
may be approved and that the Surveyors
may be so informed by telegram

[Signature] 9/10/07



© 2020

Lloyd's Register

First Report
Medical Survey
made of Report
a account of I
nd besides bel
placement of
he back of the
damage case
declined?
EPAIRS, OH

on or below the space for Committee's Minute.)

General

Sta
this sur
survey, 1

Keelons
Floors
Reverso Frames
Transoms
Breasthooks & Or
Bivets
Outside Plating
Caulking of ditto

Beams & Fastenings
Caulking
Waterways
Decks

PRESENT COND
SUMMARY OF D
Renewed
Removed an
Paired or b

Office Fee (if any)