

5c.1.8.

F.E.

red by Chief Ship Surveyor 16. 12. 08

Received from Chief Ship Surveyor...

SEL'S NAME Lt. S. S. Summersgill Rpt. June No. 7414

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	3/20"	In lieu of doubling at breaks of R. & B.
Spar Sheerstrake . .	✓	✓

Description of Framing:— Ordinary, increased to compensate
(viz., ordinary, deep, zed, channel or bulb-angle). for omission of reverse frames.

This vessel has been fitted with her machinery at Hull, and the work requiring to be done to complete the survey for classification is reported to have been satisfactorily carried out per Hull report No. 20766 attached.


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100 A 1 ("Steel") as recommended.

± 100 A 1 ("Steel")

1 Dr (Stt) Will Sub.

$\eta.B = FPT 27t \text{ APT } 12t$

FK 3BH Cam. Floyd's A & CP 841' B9' F20' Mely Aff.



16/12/08

Lloyd's Register
0023
Foundation

Quarter, 'tween Dks.,	„	„
in Hold	„	„

WEB FRAMES, In Fore Body, No. and Spacing

Angle on ditto.....	25' x 22' x
Tie Plates <i>IN CENTRE</i>	42
Deck, Material and thickness.....	25" P.P. IN
* If Iron or Steel Deck, state if whole or part, and if wood deck	