

2m, 7, 16.

Received by Chief Ship Surveyor

27.9.16

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheers Sunnyside

Rpt.

Rot-

No.

10192

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey


Repair

The Rotterdam Surveyors report that the hatches & forecables have been repaired as required, & some minor repairs alterations carried out.

The indented tank top plating under hatchways has not been dealt with at this time.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject to the indented tank top plating being dealt with.

As now, subject &c



© 2020

W758-0003

Lloyd's Register Foundation

The above for the information of the Committee