

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 21 Sept 1916 When handed in at Local Office 19 Port of Rotterdam  
 No. in Survey held at Rotterdam Date, First Survey 9 Sept Last Survey 15 Sept 1916  
 Reg. Book. 2200 on the Wood, Iron or Steel SUNNISIDE (No. of Visits 2) Master R. Strickland

TONNAGE:—  
 GROSS 447 Built at Croole By whom Croole, S.B. Reppel & Co. When 1905 6  
 UNDER DECK 217 Owners Woods, Tulou, Brown (Inc) Port belonging to London  
 NET 179 Owners' Address London  
 (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Yes Name of Dock P. V. Haro Destined Voyage London  
 WB=CellDBorDBa feet; uE&B feet; f feet; f feet; f  
 total capacity tons. FPT tons; APT tons; MT feet tons. }  
 N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 26637 Port Sld

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Year Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>100 H 2.16</u>		<u>LMC 2.13</u>
<u>S.S. Sld N 2.13</u>		<u>B.S. 2.16</u>
		<u>T.S. Sep 11.14</u>

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR repairs

Hatches and fore and aft frames renewed and partly renewed.

It has been reported that it is the owner's intention to fit the vessel with wickets for which a wooden deckhouse now has been fitted.

Nothing has been done to the indented top plating under the hatchways.

## SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder	Caulking	Sails
Rivets	Steering gear and its connections	Treenails	Equipment letter <u>G</u>
Breasthooks & Crutches	Windlass	Breasthooks & Stemson	Anchors, No. of
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	length size (on board)
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Rule length size
Floors		Stringers, Clamps & Shells ditto	Hawser & Warps
Keelsons		Salting (State if examined.) ditto	Standing & Running Rigging

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

The above for the information of the Committee

Survey Fee (per Section 95)	£	No fee	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 95)	£	charged	19
Travelling Expenses (if chargeable)	£		Received by me,
Second Surveyor's Fee (if any)	£		19

Committee's Minute FRI. SEP. 29. 1916

Character Assigned As now

Surveyor to Lloyd's Register of Shipping

TUE. 21. NOV. 1916

Lloyd's Register Foundation

W758-0064