

by Chief Ship Surveyor 16. 12. 01 Received from Chief Ship Surveyor

NAME *ss. S.S. "Grayton Group"* Report *Bel* No. *5352*

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

Survey *Final entry*

It is submitted that before this case receives the consideration of the Committee the Surveyors should be informed that it cannot be understood why the tests for the steel wire hawsers have not been certified to in accordance with the rules, per Table 22, and they should be requested to explain how the hawsers in question can be recommended to the Committee for approval for the figure 1.

*to Bel 16.12.01*

*C.H.P.*  
*16/12/01*



© 2021  
Lloyd's Register  
Foundation

W760-0252