

N.B.  
If t  
of the tan

COPY.

Lloyd's Register of British & Foreign Shipping.

71, Fenchurch Street, E.C.

20th June, 1913.

Sir,

Reverting to my letter of the 2nd July last respecting the steamer "WAIRUNA" and with reference to your report No.671 on this vessel, I have now to acquaint you that the Committee have had before them a report from the Society's Sydney Surveyor from which it would appear that the vessel has been examined in dry dock at that port and the Boiler Survey carried out. The damaged plating reported by the Melbourne Surveyor in October 1911 has not, however, been dealt with, and I shall therefore be glad if you will ascertain from the Owners and let me know what arrangements they propose to make in regard to the matter.

I am, Sir,

Your obedient Servant,

Assistant to the Secretary.

A.Morrison, Esq.,

DUNEDIN.



© 2021

Lloyd's Register  
Foundation  
W763-0052