

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

*At S.S. 'Wairuna'*

Rpt.

*Syd*

No.

*4157*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Remarks of Survey

*Condition*

Notation of s.s.No. 2 was assigned to this vessel in September last, subject to some repairs being effected to the stem plating, etc. as recommended by the Melbourne Surveyor in October 1911.

The Sydney Surveyor now reports that he has examined this vessel in drydock, and with regard to the damage it is stated that it was not convenient to carry out repairs at the present time.

It is submitted the vessel appears worthy to remain as classed with record of survey, subject to the damaged plating being dealt with and the <sup>Dunedin</sup> Sydney Surveyor should be requested to ascertain what arrangements are proposed to be made in regard to the matter.

*100A1**H. 13 Syd**Subject to**M.*

© 2021

Lloyd's Register

Foundation

W763-0053