

14.

## GOVERNMENT SERVICE.

3

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Rpt.

No.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the work so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92

Nature of Survey

S.S. No. 2 AND DAMAGE

Damage through

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....							
Removed and faired or repaired .....	8						
Faired or repaired in place .....	5	12					

Other items:-

a bronze anchor & 15 fathoms of chain cable of  
proper weight rope & test supplies & minor repairs faired and

The S.S. No. 2 has also been held and following repairs done  
due to wear and tear:-

M/M BOX  
466

It is submitted the vessel is worthy to remain classed with record  
of Survey 7.16 and notation of S.S. Chapter No 2-16  
as recommended.

100A1

7.16 Slip

S.S. No 2-16



© 2020

466-0090

Lloyd's Register

Foundation

to have record of Survey 7-16 from  
to the vessel being engaged exclusively in carrying  
out of goods whilst without