

Chief Ship Surveyor 15.11.06

Received from Chief Ship Surveyor

NAME *Stl. S.S. "Silverlip"*

Rpt. *Cff.*

No. 27735

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Survey

Damage through striking quay wall at Barrow-in-Furness and through heavy weather

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed						1	
Removed and faired or repaired.....	2						
Faired or repaired in place.....	2	2			1		

Other items:- Vessel examined in dry dock bottom cleaned & coated, Rudder rebushed, a large number of rivets renewed & minor repairs done.

It is submitted the vessel is worthy to remain as classed with record of Survey 11.06 Cff, as recommended.

100 A1
Carrying petroleum in bulk
Fitted for liquid fuel 3.03
11.06 Cff,



© 2020
15.11.06

Lloyd's Register
Foundation