

Working pressure of end plates

Area of safety valves to superheater

Are they fitted

c/c "Saragossa"

Sld. Rpt. 26 826

It is submitted the Sunderland Surveyors should be requested to state whether steam from the main boilers can enter the donkey boiler, as no mention of this is made in the report.

Chyfr 27/10/16

JWD

25/10/16

J.R.S.

© 2021

Lloyd's Register
Foundation

W775-0146

Wm M