

Received by Chief Ship Surveyor S. Y. K.

Received from Chief Ship Surveyor G. VULI

VESSEL'S NAME Steel M.Y. Sebastian Rpt. None No. 68898

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE.

Damage through Collisions

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	1						
Removed and faired or repaired.....	4						
Faired or repaired in place.....	39	6					

Other items:-

Vessel examined in / dry dock.
Bottom cleaned & coated.
Minor repairs effected.

{ The Engine Seating of this vessel has been altered to the Surveyors
Satisfaction to suit new Engines.

It is submitted the vessel is worthy to remain as classed with
record of Survey OK as recommended

100. A.I.

Carrying pet. in bulk.

OK SLE.



© 2020

Lloyd's Register
Foundation